

# CERTIFICATE OF COMPLIANCE

**Certificate Number** 20150908-SA6635  
**Report Reference** SA6635-20090613  
**Issue Date** 2015-September-08

**Issued to:** SECURITRON MAGNALOCK CORP  
10027 S 51ST ST, PHOENIX AZ 85044

**This is to certify that representative samples of** COMPONENT - SPECIAL LOCKING ARRANGEMENTS  
See Addendum Page

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.


**Standard(s) for Safety:** UL294, Access Control System Units,  
ULC-S533-08 – Canadian Standard for Egress Door Securing  
and Releasing Devices, NFPA 101 – Life Safety Code,

**Additional Information:** See the UL Online Certifications Directory at  
[www.ul.com/database](http://www.ul.com/database) for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for use as components of complete equipment submitted for investigation rather than for direct separate installation in the field. The final acceptance of the component is dependent upon its installation and use in complete equipment submitted to UL LLC.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Assistant Chief Engineer, Global Inspection and Field Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at [www.ul.com/contactus](http://www.ul.com/contactus)



# CERTIFICATE OF COMPLIANCE


**Certificate Number** 20150908-SA6635  
**Report Reference** SA6635-20090613  
**Issue Date** 2015-September-08

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Models:

Models iMXDa, iEXDa, iMXDaCH, iMXDaH, and iMXDaCA Exit Delay Systems.

.



Bruce Mahrenholz, Assistant Chief Engineer, Global Inspection and Field Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at [www.ul.com/contactus](http://www.ul.com/contactus)

